



Art Nadler, Public Information Officer
(702) 486-1100 x1139
or (775) 688-1141 x1139

12 NEVADA CONTRACTORS DISCIPLINED **BY CONTRACTORS BOARD**

(Henderson, NV) – At its meeting on Sept. 23, 2009, the Nevada State Contractors Board adjudicated cases involving 12 contractors.

Moas Enterprises, Inc., license number 45878 (Residential & Small Commercial) based out of Henderson, NV, was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to take appropriate corrective action; willful disregard of the plans and specification of a construction project; failure to include the monetary license limit and license number on a contract or proposal; and failure to establish financial responsibility. The licensee was fined \$1,600; ordered to pay investigative costs and provide a current financial statement. The license was suspended.

Atlas Construction, Ltd., license number 53500 (General Building) based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The licensee was ordered to pay investigative costs. The license limit was reduced to \$600,000.

Celis Building Systems, Inc., license number 51263 (Lathing & Plastering) and *Intrepid Iron, Inc.*, license number 67084 (Steel Reinforcing & Erection) based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to comply with a written citation; failure to keep in force a bond or cash deposit; and for the partnership, corporation, firm or association participating in a prohibited act. The licensee was fined \$1,000; ordered to pay investigative costs and ordered to make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The licenses were revoked.

Philip Joseph Pizzolato, dba Philip Pizzolato, license number 59784 (Tiling), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to take appropriate corrective action; failure to include the Residential Recovery Fund information on a contract or proposal; and failure to establish financial responsibility. The licensee was fined \$2,500; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The license was revoked.

Brookstone Landscape, Inc., license number 55662 (Landscaping), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to respond to a written request from the Board and failure to comply with the regulations of the Board. The licensee was fined \$1,000; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The license was revoked.

David Paul Moore, dba Dave Moore Construction, license number 62280 (Residential & Small Commercial) based out of Pahrump, NV, was found in violation of Nevada Revised Statute 624 for failure to comply with a written citation and failure to keep in force a bond or cash deposit. The licensee was fined \$1,000; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The license was revoked.

Scott Greg, dba Apache Contracting, license number 44438 (Carpentry, Remodeling & Repairs) based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to comply with a written citation. The licensee was fined \$500; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The license was revoked.

MG Plumbing, LLC., license number 68573 (Plumbing), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility and failure to keep in force a bond or cash deposit. The licensee was fined \$1,000; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The license was revoked.

Millennium Construction, Inc., dba MCI, license number 68863 (General Building), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for willful disregard of the laws of the State regarding industrial insurance and failure to comply with a written citation. The licensee was fined \$1,500; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The license was revoked.

Richner Air Conditioning, Refrigeration & Heating, Inc., license number 26725 (Refrigeration & Air Conditioning), based out of Boulder City, NV, was found in violation of Nevada Revised Statute 624 for failure to respond to a written request from the Board; misrepresentation; and failure to establish financial responsibility. The licensee was fined \$1,750; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The license was revoked.

Patrick Michael McEvoy, dba Consolidated Mechanical Contractors, license number 58812 (Air Conditioning), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The licensee was fined \$500; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The license was revoked.

Gibford Construction, Inc., license numbers 45562 and 62271 (Residential & Small Commercial and Carpentry), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to respond to a written request from the Board; substandard workmanship; failure to take appropriate corrective action; failure to include the Residential Recovery Fund information on a contract or proposal; failure to include the monetary license limit and license number on a contract or proposal; improper acts involving residential pools and spas; failure to discharge a lien; failure to comply with the terms of a construction contract, thereby causing material injury to another; willful disregard of the laws of the State regarding industrial insurance; failure to keep in force a bond or cash deposit; failure to establish financial responsibility; and for the partnership, corporation, firm or association participating in a prohibited act. The licensee was fined \$6,600; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund, plus fines and investigative costs. The licenses were revoked.

****The Business Review Program is one in which a contractor's business practices and regulatory compliance is examined by NSCB investigative staff. The program is a part of NSCB's proactive investigative efforts.**

The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.

###