



Nevada State Contractors Board
NEWS RELEASE

www.nscb.state.nv.us

FOR IMMEDIATE RELEASE

24-Mar-04

Contact: Sonya Ruffin, APR
(702) 486-1100 x1139
or (775) 688-1141 x1139

**CONTRACTORS BOARD TAKES DISCIPLINARY ACTION
AGAINST FIVE CONTRACTORS**

(Henderson, NV) - At its meeting on March 23, 2004, the Nevada State Contractors Board adjudicated cases against five (5) licensed contractors.

Luckier Roofing, license number 50952 (Roofing) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to comply with a notice to correct; failure to cooperate in the investigation of a complaint; failure to establish financial responsibility; and failure to include license number and monetary limit on a contract or proposal. The licensee was fined \$400, assessed the cost of investigation and ordered to make repairs.

Ericorp Construction Company Inc., license number 50745 (Residential and Small Commercial) based out of Henderson, Nevada was found in violation of Nevada Revised Statute 624 for abandonment of a construction project; failure to comply with a notice to correct; failure to establish financial responsibility; and disregard of state building laws. The licensee was fined \$2,000 and assessed the cost of investigation.

Commercial General Inc., license number 45522 (Residential and Small Commercial) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to comply with a notice to correct and failure to cooperate in the investigation of a complaint. The licensee was fined \$500, assessed the cost of investigation and ordered to make repairs.

Future Underground & Excavation, license number 49436 (Excavation, Grading, Surfacing, Wrecking Buildings, Sewers) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for failure to pay for materials or services; failure to cooperate in the investigation of a complaint; failure to comply with a request from the Board for information or records; failure to establish financial responsibility; and bidding in excess of established license limit. The Board revoked the license of Future Underground & Excavation.

Stone Creek Marble & Granite, license number 49137 (Marble) base out of Pahrump, NV was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility; failure to cooperate in the investigation of a complaint; failure to report to the Board a change in address or personnel; and failure to report to the Board a petition for bankruptcy. The Board revoked the license of Stone Creek Marble & Granite.

The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in

Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.

The Board will convene next in Reno, NV on April 6, 2004.