



Nevada State Contractors Board
NEWS RELEASE

www.nscb.state.nv.us

FOR IMMEDIATE RELEASE

23-Jun-03

Contact: Sonya Ruffin, APR
(702) 486-1100 x1139
or (775) 688-1141 x1139

BOARD TAKES DISCIPLINARY ACTION AGAINST NINE LICENSED CONTRACTORS

(Henderson, NV) – At its meeting on June 17, 2003 the Nevada State Contractors Board adjudicated cases against nine (9) licensed contractors.

Cornerstone Masonry, license number 31202 (Masonry) and license number 41425 (Residential and Small Commercial) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for failure to pay for materials or services; failure to establish financial responsibility; and failure to cooperate in an investigation of a complaint. A permanent letter of reprimand will be placed in the licensee's file and licensee was assessed the cost of the investigation.

Westview Concrete, license number 33883 (Concrete Contracting) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for substandard workmanship and failure to cooperate in the investigation of a complaint. The Board revoked the license of Westview Concrete.

Wythe Enterprises, license number 47573 (Plumbing & Heating) based out of Henderson, Nevada was found in violation of Nevada Revised Statute 624 for failure to pay for materials or services and failure to establish financial responsibility. The Board revoked the license of Wythe Enterprises.

Cheyenne Construction, Inc. license number 33804 (Residential & Small Commercial) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility; failure to keep in force a bond or cash deposit and failure to cooperate in the investigation of a complaint. The Board revoked the license of Cheyenne Construction, Inc.

Panther, Inc. license number 50137 (Lathing & Plastering) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute 624 for failure to pay for materials or services; failure to establish financial responsibility and failure to cooperate in the investigation of a complaint. The Board revoked the license of Panther, Inc.

Commercial Installations, Inc. license number 47956 (Metal Doors & Frames, Metal Windows & Frames, Store Fronts) based out of North Las Vegas, Nevada was found in violation of Nevada Revised Statute Chapter 624 for failure to pay for materials or services; failure to establish financial responsibility; failure to notify the Board of a change of address; failure to keep in force a bond or cash deposit and failure to cooperate in the investigation of a complaint. The Board revoked the license of Commercial Installations, Inc.

Desert Valley Tile & Marble, Inc. license number 49927 (Tiling) and license number 49928 (Terazzo & Marble) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute Chapter 624 for abandonment a construction project; failure to establish financial responsibility; failure to cooperate in the investigation of a complaint; failure to provide required disclosures; failure to include license number and monetary limit on a bid or contract and failure to notify the board of a change in address. The Board revoked the license of Desert Valley Tile & Marble, Inc.

Delfino Electrical, license number 36505 (Electrical Contracting) based our of Henderson, Nevada was found in violation of Nevada Revised Statute Chapter 624 for failure to pay for materials or services, failure to establish financial responsibility; failure to cooperate in the investigation of a complaint; failure to keep in force a bond or cash deposit and failure to notify the board of a change of address. The Board revoked the license of Delfino Electrical.

Capitol Builders & Development, license number 40101 (Residential & Small Commercial) based out of Las Vegas, Nevada was found in violation of Nevada Revised Statute Chapter 624 for substandard workmanship; failure to comply with a notice of correct; abandonment of a construction project; failure to notify the Board of a change of address; failure to provide the required disclosures; failure to include license number and monetary limit on a bid or contract; failure to cooperate in the investigation of a complaint; acting beyond the scope of the license; failure to provide residential recovery fund disclosures; failure to comply with the building laws of the state. The Board revoked the license of Capitol Builders & Development.

The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.

The Board will convene next in Reno, NV on July 8, 2003.