



Art Nadler, Public Information Officer  
(702) 486-1100 x1139  
or (775) 688-1141 x1139

## **14 NEVADA CONTRACTORS DISCIPLINED** **BY CONTRACTORS BOARD**

(Henderson, NV) – At its meeting on Jan. 27, 2010, the Nevada State Contractors Board adjudicated cases involving 14 contractors.

---

***A 1 Action Plumbing and Rooter, Inc.***, license number 50591 (Plumbing & Heating) based out of Henderson, NV, was found in violation of Nevada Revised Statute 624 for misrepresentation of a material fact and failure to comply with a written citation. The licensee was fined \$4,000 and ordered to pay investigative costs. The license remains suspended, until corporate status with the Secretary of State is reinstated and fines and investigative costs paid.

---

***Nevari, Inc., dba Nevari Air***, license number 66097 (Refrigeration & Air Conditioning) based out of North Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for misrepresenting the value of services. The licensee was fined \$4,000; ordered to pay investigative costs; ordered to pay \$300 in restitution and send a letter to American Home Shield stating that there is no disposal law.

---

***Southern Nevada Pools, LLC.***, license number 47317 (Commercial & Residential Pools) based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to respond to a written request from the Board; substandard workmanship; failure to take appropriate corrective action; failure to include the Residential Recovery Fund information on a contract or proposal; and failure to establish financial responsibility. The licensee was fined \$3,000; ordered to pay investigative costs and ordered to make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

---

***Schulter Electric, Inc.***, license number 51466 (Electrical Contracting), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The licensee was fined \$500; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

---

***Thunder River, Inc.***, license number 52076 (Residential & Small Commercial), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The licensee was fined \$500; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

---

***Crowne Closets, Inc., dba Crowne Closets & Cabinetry***, license number 68054 (Finish Carpentry) based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to comply with the terms of a construction contract, thereby causing material injury to another; failure to include the Residential Recovery Fund information on a contract or proposal; failure to include the monetary license limit and license number on a contract or proposal; and failure to establish financial responsibility. The license was revoked.

---

***Mana Builders, LLC.***, license number 62187 (Residential & Small Commercial), based out of Las Vegas, NV; was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The licensee was fined \$500; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

---

***Royal Plaster, LLC.***, license number 69528 (Coatings of Stucco & Cement), based out of Henderson, NV, was found in violation of Nevada Revised Statute 624 for failure to respond to a written request from the Board and failure to establish financial responsibility. The licensee was fined \$1,500; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

---

***Copper City Construction, LLC.***, license numbers 68802 and 69199 (Residential & Small Commercial and Carpentry), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to respond to a written request from the Board; failure to establish financial responsibility; and for the partnership, corporation, firm or association participating in a prohibited act. The licensee was fined \$1,500; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The licenses were revoked.

---

***Atlas Construction, LTD.***, license number 53500 (General Building), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to pay money due for materials or services; failure to respond to a written request from the Board; and failure to comply with the regulations of the Board. The licensee was fined \$1,000; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

---

***Southern Nevada Mechanical Company***, license number 52530 (Refrigeration & Air Conditioning), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to respond to a written request from the Board and failure to establish financial responsibility. The licensee was fined \$1,000; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

---

***Thunder Air***, license number 58397 (Refrigeration and Air Conditioning), based out of Henderson, NV, was found in violation of Nevada Revised Statute 624 for failure to respond to a written request from the Board and failure to establish financial responsibility. The licensee was fined \$1,000; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

---

***Regen Clay Gubler, dba R.C. Gubler***, license number 48413 (Residential & Small Commercial), based out of North Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for a crime involving moral turpitude and failure to establish financial responsibility. The licensee was fined \$2,000; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

---

***Macias Enterprises, LLC., dba Southwest Flooring***, license numbers 68096 and 64826 (Tiling and Finishing Floors), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to comply with a written citation and for the partnership, corporation, firm or association participating in a prohibited act. The licensee was fined \$500; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The licenses were revoked.

---

**\*\*The Business Review Program is one in which a contractor's business practices and regulatory compliance is examined by NSCB investigative staff. The program is a part of NSCB's proactive investigative efforts.**

---

***The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.***

---

###