



NSCB News Release



FOR IMMEDIATE RELEASE
June 24, 2013

CONTACT: Jennifer Turner
Public Information Officer
(702) 486-1139

Scott Smith
Public Information Specialist
(702) 486-1165

SIX CONTRACTORS DISCIPLINED BY CONTRACTORS BOARD

HENDERSON and RENO, Nev. – At its June hearings in Reno and Henderson, the Nevada State Contractors Board took action against several licensed contractors for violations of Nevada Revised Statutes Chapter 624.

Siding Innovations, Inc., license number 68416 (carpentry, remodeling, and repairs), based out of Reno, Nev., was ordered to pay investigative costs and the monetary license limit was reduced to \$180,000. Costs must be paid within the time ordered by the Hearing Officer or the license will be suspended.

Ital Stone, Inc., license numbers 53369 (install terrazzo & marble) and 58861 (tiling), and ***Stone Industries of America, LLC***, license numbers 75856 (tiling) and 75857 (install terrazzo & marble), both based out of Las Vegas, Nev., were found in violation for failure to prosecute a construction project or operation thereby causing material injury to another; failure to complete a construction project in accordance with the plans and specifications; failure to include the Residential Recovery Fund information on a contract or proposal; failure to keep in force a bond or cash deposit; contracting on a suspended or revoked license; and failure to demonstrate financial responsibility. The Hearing Officer ordered license numbers 53369 and 58861 remain suspended. The licensee is to make restitution to the complainant in the amount of \$20,000.

Access Door and Glass, LLC, dba Access Glass, license number 64736 (glass and glazing) based out of Las Vegas, Nev., was found in violation for failure to establish financial responsibility and failure to respond to a written request from the board. The license was revoked. Licensee was fined \$750, assessed investigative costs and required to make restitution to damaged parties.

Extreme Automation, Inc., license number 67124 (low voltage) based out of Las Vegas, Nev., was found in violation for abandonment without legal excuse of any construction project; failure to comply with the terms of a construction contract thereby causing material injury to another; failure to take appropriate corrective action; willful disregard of the state's building laws; failure to establish financial responsibility; failure to include the monetary license limit or license number contract or proposal; failure to comply with a written citation within the time permitted for compliance; and acting in the capacity of a contractor beyond the scope of the license. The license was revoked. Licensee was fined \$5,350, assessed investigative costs and required to make restitution to damaged parties.

Taylor Refrigeration & HVAC, license number 57909 (refrigeration & air conditioning) based out of Las Vegas, Nev., was found in violation for failure to establish financial responsibility and failure to keep in force a bond or cash deposit. The license was revoked.

(more)

Licensee was fined \$1,000, assessed investigative costs and required to make restitution to damaged parties.

Pepco Flooring, Inc., license numbers 72724 (tiling), 72582 (finish carpentry limited to wood floors) and 72583 (carpet laying), based out of Henderson, Nev., was found in violation for failure to establish financial responsibility and failure to keep in force a bond or cash deposit. The license was revoked. Licensee was fined \$2,000, assessed investigative costs and required to make restitution to damaged parties.

The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.

#

STAY CONNECTED

Visit our website: www.nscb.nv.gov

Join our social media network to receive current industry updates:

