



Art Nadler, Public Information Officer
(702) 486-1100 x1139
or (775) 688-1141 x1139

EIGHT NEVADA CONTRACTORS DISCIPLINED **BY CONTRACTORS BOARD**

(Henderson, NV) – At its meetings on Sept. 22 and 23, 2010, the Nevada State Contractors Board adjudicated cases involving eight contractors.

Cole Wilson, license number 54959 (Residential & Small Commercial), based out of Monrovia, CA, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility and failure to respond to a written request from the Board. The licensee was ordered to pay investigative costs.

Sierra Stucco, Inc., license number 55993 (Lathing & Plastering), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to take appropriate corrective action; failure to respond to a written request from the Board; failure to include the Residential Recovery Fund information on a contract or proposal; and failure to establish financial responsibility. The licensee was fined \$2,350; ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

S. W. D. Enterprises, dba The Shotcrete Professionals, license number 53447 (Spraying Mix Containing Cement), based out of North Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The licensee was fined \$500 and ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

J. G. Plastering, LLC., license number 55293 (Lathing & Plastering), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility and failure to keep in force a bond or cash deposit. The licensee was fined \$1,000 and ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

Riggio Brothers Construction, Inc., license number 49783A (Carpentry), based out of Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The licensee was fined \$500 and ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

Exotic Millworks, Inc., license number 71306 (Carpentry), based out of North Las Vegas, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility and failure to keep in force a bond or cash deposit. The licensee was fined \$1,000 and ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The license was revoked.

Smart Pools, Inc., license number 40768A (Commercial & Residential Pools) and **David L. Klohr, dba David L. Klohr General Contractor**, license number 40767 (Residential & Small Commercial), based out of Las Vegas, NV, were found in violation of Nevada Revised Statute 624 for failure to comply with a written citation and for the partnership, corporation, firm or association participating in a prohibited act. The licensee was fined \$500 and ordered to pay investigative costs and make full restitution to all damaged parties and reimburse the Board for any monies paid out of the Residential Recovery Fund. The licenses were revoked.

Stuart Stout Roofing, Inc., dba Roof Tec, license number 67444 (Roofing), based out of St. George, Utah, was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to take appropriate corrective action; failure to include the Residential Recovery Fund information on a contract or proposal; and failure to include the monetary license limit and license number on a contract or proposal. The licensee was ordered to pay investigative costs and provide written monthly updates regarding workmanship at the homeowner's residence. The license limit was lowered to \$400,000.

****The Business Review Program is one in which a contractor's business practices and regulatory compliance is examined by NSCB investigative staff. The program is a part of NSCB's proactive investigative efforts.**

The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.

###