

e-News

Release

Nevada State Contractors Board

www.nscb.state.nv.us



Art Nadler, Public Information Officer
(702) 486-1100 x1139
or (775) 688-1141 x1139

FOUR NEVADA CONTRACTORS DISCIPLINED **BY CONTRACTORS BOARD**

(Reno, NV) – At its meeting on Jan. 13, 2010, the Nevada State Contractors Board adjudicated cases involving four contractors.

Adept Landscaping, license number 57198; *Adept Concrete and Pavers*, license number 60896 and *Adept Painting*, license number 52161 (Landscaping, Concrete Contracting and Painting) based out of Reno, NV, was found in violation of Nevada Revised Statute 624 for substandard workmanship; failure to comply with the Board's notice to correct; failure to include the Residential Recovery Fund information on a contract or proposal; and failure to establish financial responsibility. The licensee was fined \$400; ordered to pay investigative costs; pay the injured party \$7,000; and provide the Board with a financial review. Limits on license numbers 57198 and 60896 were lowered to \$50,000 each.

J K B Paramount Homes Nevada, LLC., license number 59317 and *J K B Nevada, Inc.*, license number 59316 (Residential & Small Commercial) based out of Turlock, CA, were found in violation of Nevada Revised Statute 624 for failure to comply with the terms of a construction contract, thereby causing material injury to another; failure to comply with the Board's notice to correct; failure to include the Residential Recovery Fund information on a contract or proposal; failure to keep in force a bond or cash deposit; for the partnership, corporation, firm or association participating in a prohibited act; and failure to establish financial responsibility. The licensee was fined \$1,600; ordered to pay investigative costs; and pay the injured party \$6,000. The licenses were revoked.

-- more --

Nevada Granite Industries, Inc., dba Granite Transformations of Reno, license number 59698 and *Nevada Granite Industries, Inc., dba Granite Transformations of Reno*, license number 72047 (Install Terazzo & Marble and Finish Carpentry) based out of Reno, NV, was found in violation of Nevada Revised Statute 624 for substandard workmanship; abandonment; failure to comply with the Board's notices to correct; failure to notify the Board of a change in address or personnel within 30 days of the change; failure to keep in force a bond or cash deposit; for the partnership, corporation, firm or association participating in a prohibited act; and failure to establish financial responsibility. The licensee was fined \$3,250; ordered to pay investigative costs and make full restitution to all damaged parties. The licenses were revoked.

Shane E. Bryant., license number 58616 (Residential & Small Commercial), based out of Reno, NV, was found in violation of Nevada Revised Statute 624 for failure to establish financial responsibility. The licensee was ordered to pay investigative costs.

****The Business Review Program is one in which a contractor's business practices and regulatory compliance is examined by NSCB investigative staff. The program is a part of NSCB's proactive investigative efforts.**

The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.

###