

## NSCB News Release



## FOR IMMEDIATE RELEASE

June 3, 2014

**CONTACT:** <u>Jennifer Turner</u> <u>Scott Smith</u>

Public Info. Officer Public Info. Specialist

(702) 486-1139 (702) 486-1165

## BOARD REVOKES TWO LICENSES, DISCIPLINES SEVERAL CONTRACTORS

**HENDERSON, Nev.** –At its May 29 Disciplinary Hearing, the Nevada State Contractors Board revoked two licenses and took action against five other licensed contractors for violations of Nevada Revised Statutes Chapter 624.

**Olson Iron**, license number 60513 (steel reinforcement and erection) based out of Las Vegas, Nev., was found in violation for failure to comply with the terms of a construction contract thereby causing material injury and diversion of funds. The licensee was fined \$1,250 and assessed investigative costs.

**B.O.L.M.C., dba Briana's Design Center**, license numbers 58720 (finishing floors), 58721 (tiling) and 59605 (terrazzo and marble installation) based out of Las Vegas, Nev., was found in violation for aiding or abetting an unlicensed person, knowingly entering into a contract with an unlicensed contractor, failure to include the license number or monetary limit on a bid or contract, failure to establish financial responsibility and commission of a fraudulent or deceitful act. The licensee was fined \$2,600 and assessed investigative costs. The license limit was reduced to \$45,000.

**Mold Doctor, LLC**, license number 68357 (taping and finishing and drywall) based out of Las Vegas, Nev., was found in violation for substandard workmanship, failure to include the license number or monetary limit on a bid or contract, failure to include Residential Recovery Fund information on a contract or proposal, acting in the capacity of a contractor beyond the scope of the license and failure to establish financial responsibility. The license was suspended pending submission of a financial statement. Licensee was fined \$1,200 and assessed investigative costs.

*Murrell E. Redding, Jr., dba Redding Drilling*, license number 38155 (drilling wells and installing pumps, pressure tanks and storage tanks) based out of Las Vegas, Nev., was suspended pending a hearing on July 23.

**Spike Construction**, license number 59148 (residential and small commercial) based out of Las Vegas, Nev., was found in violation for willful disregard of the state's building laws (two counts), failure to include Residential Recovery Fund information on a contract or proposal and failure to establish financial responsibility. Licensee was fined \$3,000 and assessed investigative costs.

Geoffrey Burnet Shaw, dba Silver City Construction, license number 13923 (general building) and Silver City Air Conditioning, license number 25808, based out of Las Vegas, Nev., was found in violation for substandard workmanship, failure to comply with the provisions of the Board, failure to respond to a written request from the Board, willful disregard of the state's building laws and failure to establish financial responsibility. The licenses were revoked. Licensee was fined \$2,300 and assessed investigative costs.

**Foothill Fire Protection, LLC**, license number 77496 (fire alarms) based out of Las Vegas, Nev., was found in violation for willful disregard for the state's building laws, failure to respond to a written request from the Board and failure to establish financial responsibility. Licensee was fined \$1,000 and assessed investigative costs.

*Sambrok, LLC*, license number 77244 (finish carpentry), based out of Las Vegas, Nev., was found in violation for substandard workmanship, failure to comply with the provisions of the Board and failure to establish financial responsibility. The license was revoked. Licensee was fined \$1,050 and assessed investigative costs.

The Nevada State Contractors Board is committed to protecting the public's health, safety, and welfare through licensing and regulation of the construction industry. Under Nevada Revised Statutes, a licensee is subject to disciplinary action by the Board for failure to comply with the

requirements of the laws or regulations governing contractors. Violations may result in Board action against the contractor's license. The State Contractors Board has the power to regulate contractors and discipline licensees who violate NRS 624. Disciplinary action may consist of a fine of up to \$10,000 per offense, order corrective action, suspension, revocation or other action.

###

## **STAY CONNECTED**

Visit our website: <a href="https://www.nscb.nv.gov">www.nscb.nv.gov</a>

Join our social media network to receive current industry updates:

